Sanitized Copy Approved for Release 2011/09/19 : CIA-RDP78-03424A001100040114-1

NOT RELEASABLE TO FOREIGN NATIONALS

CON	5	RI"	7	A	A
UUIV		Ŋ		А	L

R. + D-003

Chief, Installation and Maintenance Branch

IAN 8

Chief, Research and Development Branch

Audio Responso Curve

1. In October 1958 an audio response curve was run to determine the characteristics of the voice quality, audio test line.

The audio line characteristics were not suitable for a data transmission link between the Receive RF Terminal and the Receive Data Terminal due to interference on the line. The telephone corpany is now providing a termination at the Signal Center in The Duilding. It is hoped that the new termination will eliminate unwanted interference on the line.

2. It is requested that an audio response curve be run to determine the characteristics of the audio test line, after the new termination is made in "I" Duilding.

OC-E/R&D-EP/PCV:wlj cc: R&D Subject File

(7 January 1959)

R&D Chrono EP Chrono

CONTIDENTIAL

NOT RELEASABLE TO FOREIGN NATIONALS

Sanitized Copy Approved for Release 2011/09/19 : CIA-RDP78-03424A001100040114-1

25X1

25X1

²25X1

25X1

25X1

25X1